lame of Inspector: Frank Donroe	Signature: 2 Conse		
Date of Inspection: 2-11-22	Time inspection started: 2pm		
L) UPON COMPLETION, RETURN THIS FORM AND REPORT ALL IDE	NTIFIED PROBLEMS IMMEDIATELY TO THE V	VEP COORDINATOR.	
Key: Satisfactory - S, Not Applicable - NA, See Comment Section - C	AREAS SUBJECT TO INSPECTION		Additional Comments
	Southside of Bldg.	Northside of Bldg.	
Process Wastewater Management			
are there any hoses or signs of washing of vehicles or equipment (e.g. loats) outside?	S	S	
nterview one employee to assiss compliance with this policy?			Name: Jeff xx
s there a posting inside the building notifying workers of proper process waste water management?	S	S	
Are there posting outside the building notifying workers of proper process wastewater management	S	S	

IMMEDIATELY CONTACT THE WEP COORDINATOR WITH ANY IDENTIFIED DEFICIENCIES AT (516) 204.5093. IF NOT AVAILABLE CONTACT SECURITY AT GATE 6 BACK STRETCH AT (718) 641.7400 OR AQUEDUCT MAIN SECURITY AT (718)659.3511