Name of Inspector: Mark A. Randazzo/O'Brien & Gere Engineers Signature:

Date of Inspection: March 1, 2017 Time Inspection Started: 0915 hours Facility Status: Not a Racing day

1) UPON COMPLETION, RETURN THIS FORM AND REPORT ALL IDENTIFIED PROBLEMS IMMEDIATELY TO THE WEP COORDINATOR.

Key: AREAS SUBJECT TO INSPECTION																
Satisfactory – S, Not Applicable – NA See Comment Section – C	Barn	Pony	Cafeteria	Additional Comments (Deficiencies and Remedies)												
Process Wastewater Management	1	2	3	4	5	6	7	8	9	10	11	12	12A	Barn	Bldg.	
Are there any signs that horse washing has been conducted outside of the designated washing stalls?	S	S	S	S	S	S	S	S	S	S	S	S	S	S	NA	
Are there any hoses or wash buckets observed outside the barns?	S	S	S	S	S	С	S	S	S	S	S	S	S	S	NA	Barn 6 grooms contacted at time of inspection to remove buckets.
Are rubber mats being washed outside of the horse wash stalls?	S	S	S	S	S	S	S	S	S	S	S	S	S	S	NA	
Are there signs that vehicle/equipment washing has taken place in the horse barn area? Horse vans?	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	
Are WEP signs posted at each end of the barn and middle?	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	
Do storm drains have the words <i>Storm Drain – No Wastewater</i> stenciled nearby?	S	С	S	S	S	S	S	S	S	S	S	С	С	S	NA	Barn 2, and two drains between 12 and 12A are not labeled.
Are horse washing stalls operational?	S	S	S	S	S	S	S	S	S	S	S	S	S	S	NA	
Are chemicals being handled and disposed of in a manner sufficient to prevent pollutants from entering the stormwater conveyance system?	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	
Are barns free of outside water spigots with the exception of the west side of Barn 11? (State Gaming Commission)	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	
Dumpster Management																
Is ground around manure/bedding dumpsters free of manure and bedding?	S	S	S	С	S	S	S	С	С	С	S	S	S	S	NA	Minor amounts noted near bins 4, 8, 9, and 10.
Are there signs that dumpsters are releasing residual liquid to the ground?	S	S	S	S	S	S	S	S	S	S	S	S	S	S	NA	
Do any dumpsters appear to be at capacity or in need of emptying?	S	S	S	S	S	S	S	S	S	S	S	S	S	S	NA	
Stormwater Management / Diversionary Equipment																
Are gutters and downspouts in good condition and free of debris?	S	S	S	S	S	S	С	С	S	С	S	S	S	S	С	Barn 7 two downspouts missing. Barn 8 downspout missing. Barn 10 horizontal section of gutter missing. Maintenance Bldg. next to cafeteria has a broken downspout. Repairs are on-going.
Do stormwater drains show signs of improper wastewater disposal?	S	S	S	S	S	S	S	S	S	S	S	S	S	S	S	

Real-Time Dry Weather Monitoring Equipment	
Are solar powered wet sensors in northern and southern stormwater catch basins functional?	Yes/Yes
Is pump runtime meter on wet well pump control panel functioning? Is the daily log being filled out?	Runtime hour meter readings – Pump No. 1 - 139 hours, Pump No. 2 - 113 hours

IMMEDIATELY CONTACT THE WEP COORDINATOR WITH ANY IDENTIFIED DEFICIENCIES AT (516) 204-5093. IF NOT AVAILABLE CONTACT SECURITY AT GATE 6 BACK STRETCH AT (718) 641-4700 OR AQUEDUCT MAIN SECURITY AT (718) 659-3511.

Additional Notes: Washer machine noted in Barn 3 across from Stall 19, but not connected to the horse wash stall drain. No active discharge noted during this inspection or last week's inspection. Barn and Maintenance Supervisors contacted.