NEW YORK RACING ASSOCIATION - AQUEDUCT RACETRACK | WEEKLY EQUIPMENT BUILDING WEP INSPECTION RECORD

Name of Inspector:	Mark A. Randazzo/O'Brien & Gere Engineers	Signature:
Date of Inspection:	February 17, 2017	Time of Inspection: 1500 hrs

1) UPON COMPLETION, RETURN THIS FORM AND REPORT ALL IDENTIFIED PROBLEMS IMMEDIATELY TO THE WEP COORDINATOR.

Key:	AREAS SUBJECT TO INSPECTION		Additional Comments
Satisfactory – S Not Applicable – NA See Comment Section – C	Southside of Bldg.	Northside of Bldg.	
Are there any hoses or signs of washing of vehicles or equipment (e.g., floats) outside?	S	S	
Interview one employee to assess compliance with this policy?			Name: Frank Donroe
Is there a posting inside the building notifying workers of proper process wastewater management?	S	S	Sign is posted at entrance door leading to office, lavatory, and breakroom.
Are there postings outside the building notifying workers of proper process wastewater management?	S	S	Posted outside of garage bays on both sides of building.
Other issues:			

IMMEDIATELY CONTACT THE WEP COORDINATOR WITH ANY IDENTIFIED DEFICIENCIES AT (516) 204-5093. IF NOT AVAILABLE CONTACT SECURITY AT GATE 6 BACK STRETCH (718) 641-4700 (ASK OPERATOR) OR AQUEDUCT MAIN SECURITY AT (718) 659-3511.